



Electron



Electrostatic Powder Coating



C1 & C2 Manual Gun Cleaning Guide

- Tools Required = Air Compressor, Gun Cleaning Brush
- Gun Cleaning Recommended After an 8 hour Shift


- Remove Threaded Sleeve, Nozzle & Electrode (Check for Wear N Tear)
- Use Clean, Dry, Compressed Air to Clean Inside & Outside



- Remove Powder Hose Connection from Gun



- Use A Cleaning Brush to Clean Inside of the Powder Tube of Your Gun & The Barrel of Your Gun Body



- Rotate Cleaning Brush When Using



- Use Clean, Dry, Compressed Air Through The Powder Tube & Powder Hose



- Put Gun Back Together, then Clean/Blow Off the Outside of the Gun